# BELZONA REBUILDS THE UNDERSIDE OF PULPMILL FLOOR

## **CUSTOMER**

Pulp & Paper Operation, BC, Canada

#### APPLICATION DATE

June 2003

# **APPLICATION SITUATION**

Badly damaged underside of concrete floor

#### **PROBLEM**

Moisture, vibration and impact from above had caused the underside of this concrete deck to spall badly leaving exposed corroding rebar

#### **PRODUCTS**

Belzona® 4141 (Magma Build)

#### **SUBSTRATE**

Concrete and steel reinforcement bars

## **APPLICATION METHOD**

Application carried out using a modified version of Belzona Know-How System Leaflet FPA-1

## **BELZONA FACTS**

Using Belzona® 4141 allowed the underside of the floor to be rebuilt in a single application without the need for forms saving many additional hours of downtime when compared with a conventional repair. Footnote: The damaged sections on the top side of the deck were rebuilt in 2002 with Belzona® 4111 (Magma Quartz) and the complete deck area sealed with Belzona® 5122 (Clear Cladding)

### **PICTURES**

- 1. View of corroded rebar and spalled concrete underside
- 2. A partially completed underside showing the unfinished section after grit blasting to remove all corrosion from the rebar
- 3. Application in final stages of completion







For more examples of Belzona Know-How In Action, please visit http://khia.belzona.com



BELZONA®
Repair • Protect • Improve