BELZONA REPAIRS OIL LEAK ON TRANSFORMER FIN

CUSTOMER

Electricity Distribution Co. UK

APPLICATION DATE

2008

APPLICATION SITUATION

Oil cooled electrical transformer

PROBLEM

Oil leaking from fins

PRODUCTS

Belzona 1161 (Super UW-Metal)

SUBSTRATE

Steel

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11a.

BELZONA FACTS

The costly need to drain down the oil to effect a repair was eradicated. The Belzona repair was carried out in less than 2 hours and has proven to be totally successful.

PICTURES

- 1. General view of the transformer
- 2. Close up of oil leak area
- 3. Completed application. Leak sealed with Belzona 1161







ა.

For more examples of Belzona Know-How In Action, please visit http://khia.belzona.com

