# BELZONA BELT REPAIR KEEPS MINE PRODUCING

#### **CUSTOMER**

Mine, Central Missouri

#### APPLICATION DATE

June, 2008

## **APPLICATION SITUATION**

Conveyor belt at aggregates.

#### **PROBLEM**

A large rock found its way between the drive roller & the belt, resulting in extensive damage to belt. Minimizing downtime was crucial!

### **PRODUCTS**

Belzona® 2211 (MP Hi Build Elastomer)

### **SUBSTRATE**

Rubber Conveyor Belt

# **APPLICATION METHOD**

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-1. The belt was cleaned, degreased, and undercut 1/4" x 3" wide on all sides of damaged area. Reinforcement tape was embedded in the Belzona® 2211 for additional strength.

## **BELZONA FACTS**

The cost of downtime and new belting was significant and customers production schedule did not allow for replacement. This repair was completed in a fraction of the time needed to replace the belt. Customer experienced significant savings in downtime and replacement costs.

## **PICTURES**

- 1. Attempts to prevent belt from tearing further
- 2. Belt cleaned and undercut
- 3. Former with weights in place to form repair smooth and flush with belt surface
- 4. Repair completed









For more examples of Belzona Know-How In Action, please visit http://khia.belzona.com



UK • USA • Canada • China www.belzona.com

