

BELZONA REPAIRS PROFILE OF HYDROELECTRIC DAM

CUSTOMER

Washington, USA

APPLICATION DATE

October 2012

APPLICATION SITUATION

Rebuilding the profile of a small hydroelectric dam.

PROBLEM

The profile of a small hydroelectric dam became worn, exposing reinforcing bar, which was caused by damage from VW Beetle sized boulders tumbling into and over the face of dam during spring runoff. The client was concerned about maintaining the integrity of the small hydroelectric dam and restoring the original profile.

PRODUCTS

Belzona 4111 (Magma-Quartz)

SUBSTRATE

Concrete and exposed reinforcing bar

APPLICATION METHOD

With the help of plywood templates, the dam profile was rebuilt with Belzona 4111 applied by hand. The application time was limited due to possible mountain runoff. Work was tightly monitored and contained so as not to pollute nearby fish spawning grounds.

BELZONA FACTS

The client was previously familiar with the bond strength and mechanical properties of Belzona 4111. Several other comparable materials had been considered.

PICTURES

1. Dam (ogee) profile before repairs
2. Several pallets of Belzona 4111 on site
3. Dam repairs underway - note templates & mixer
4. Completed application



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve