

BELZONA SEALS BROKEN SKYLIGHTS

CUSTOMER

Office building, Bielsko-Biala, Poland

APPLICATION DATE

July 2009

APPLICATION SITUATION

Roof above the office space has 4 large skylights.

PROBLEM

Due to sun exposure the seals had broken around the fastening bolts causing water leakage into the building each time it rained.

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Bitumen

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-3.

BELZONA FACTS

Repair cost less than half the purchase and replacement costs of new skylights. Inspected in August 2016 repairs still in excellent condition and keeping offices dry.

PICTURES


1. Washing damaged skylights
2. Application of Belzona 3111 onto the Belzona 3911 Conditioner
3. Rooftop view immediately after the repair.
4. Rooftop view August 2016



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve