

## SF6 GAS LEAK REPAIR

### CUSTOMER

Wind farm, Australia

### APPLICATION DATE

May-21

### APPLICATION SITUATION

In a wind farm in Australia, SF6 gas leaks were observed on flanges and needed to be sealed.

### PROBLEM

SF6 gas leaks were observed on flanges and needed to be sealed to prevent further leakage of this extremely potent greenhouse gas.

### PRODUCTS

Belzona 1161 (Super UW-metal)

Belzona 5831 (ST-Barrier)

### SUBSTRATE

Steel

### APPLICATION METHOD

Surface was prepared with power tools, such as bristles blasters and grinders to achieve a good profile for the Belzona to adhere. Belzona 1161 and reinforcing tape was applied around the outside of the flange. Then all nuts and bolts were coated with Belzona 1161. Belzona 5831 was then applied over the Belzona 1161 repair area to ensure a good seal and dress up the application

### BELZONA FACTS

8 Flanges were successfully repaired, the client was happy and additional repairs will be carried out soon.

### PICTURES

1. Wind farm
2. Leaking flange
3. Application of Belzona 1161 & 5831
4. Completed flange gas leak repair



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

Copyright © Belzona International Limited 2021

  
**BELZONA**  
Repair • Protect • Improve