

BELZONA REPAIR TO CRACKED GLAND SEAL IN FOSSIL PLANT

CUSTOMER

Fossil Plant in Maryland

APPLICATION DATE

October 1995

APPLICATION SITUATION

Gland seal in feed pump

PROBLEM

Gland seal had a cracked casing. The condensate used in the gland seal system was leaking and causing a safety problem.

PRODUCTS

Belzona® 1111 (Super Metal)

SUBSTRATE

Cast Iron

APPLICATION METHOD

In accordance with Belzona Know-How System Leaflet CEP-1.

BELZONA FACTS

Welding had been considered as a possible solution but was ruled out. A new casting would have cost \$32,000 and would not have been available for several weeks. Using Belzona saved the customer most of this expense plus a huge reduction in downtime.

PICTURES

1. Main Feed Pump - note rust around the gland
2. Casting on work bench prior to surface prep
3. Application of Belzona® 1111



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

