

BELZONA PUMP REPAIR PROVIDES OVER TEN YEARS OF UNINTERRUPTED SERVICE

CUSTOMER

Paper Company in Georgia

APPLICATION DATE

November 1986

APPLICATION SITUATION

Primary fan pump

PROBLEM

Pump suffered from erosion/corrosion and was completely destroyed after four years of operation

PRODUCTS

Belzona® 1311 (Ceramic R Metal)

Belzona® 1321 (Ceramic S Metal)

SUBSTRATE

Cast iron

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets CEP-1, CEP-2 and CEP-3.

BELZONA FACTS

Pump replacement cost is \$60,000.00. Cost of Belzona repair: \$9,300.00. After more than ten years of uninterrupted service, the pump is still in use and twice required only minor touch-ups. An impressive savings of three pump replacements.

PICTURES

1. Severe damage
2. The wear ring seats rebuilt, clamps help ensure proper alignment
3. Belzona® 1321 (Ceramic S Metal) coating



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

