

BELZONA REPAIR TO INTERNAL ROOF DRAIN STILL OK 24 YEARS LATER

CUSTOMER

Auto manufacturer, Wentzville, MO

APPLICATION DATE

Summer 1984

APPLICATION SITUATION

Internal downpipe, part of roof drainage system.

PROBLEM

Hit by a fork lift truck, the pipe broke off at the floor level and leaked water everytime it rained.

PRODUCTS

Belzona® 4111 (Magma Quartz)

SUBSTRATE

Steel and concrete

APPLICATION METHOD

Application carried out in accordance with a modified Belzona Know-How System Leaflet VPF-11b. Belzona® 4111 was packed around the break.

BELZONA FACTS

To change the broken pipe would involve a pipefitting/labor crew at least a week to excavate down below the floor three feet. Belzona application took just 20 minutes to complete. 8 man crew, 40 hours labor at \$50.00/hr = \$16,000 saved. Revisited February 2008, still performing.

PICTURES

1. Broken pipe, summer 1984
2. Repair completed
3. Revisited February 2008 and still performing



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

