

BELZONA GIVES LIFE TO PUMP


ID: 1096

Industry: Power
Application: ENC-Engines and Casings
Substrate: Cast iron
Products: Belzona® 1111 (Super Metal)

Customer Location: Power Plant, Russia
Application Date: June, 1998

Problem

Due to inaccurate assembling of suction pipe and pressure pipe both suction and pressure flanges were torn off the pump body.



Photograph Descriptions

* Pump lost its flanges , * Flanges are in place again with Belzona® 1111 , * The pump is restored ,

Application Situation

Large pump 16 NDN working in drainage system.

Application Method

Flanges were rebuilt from pieces. All cracks in the pump casing were detected, cut out and fixed in accordance with Belzona Know-How System Leaflet ENC-1. Steel reinforcing plates were made. Flanges and reinforcing plates were fixed with Belzona® 1111 and secured with screws.

Belzona Facts

Repair work took 36 hours. Pressure testing of the pump at test bench showed full impermeability. Put back into operation and worked more than 2 years until planned replacement. With Belzona solution the customer avoided serious losses from new pump purchase and long downtime. Full repair cost only 10% of new pump price.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2025