PUMP BELL CASING REPAIRED AND PROTECTED WITH A LONG TERM BELZONA SOLUTION

ID: 1369

Industry: Power

Customer Location: National Electricity Provider, Malta

Application: CEP-Centrifugal Pumps

Application Date: May 2000

Substrate: Cast Iron

Products: * Belzona® 1311 (Ceramic R-Metal),

* Belzona® 1321 (Ceramic S-Metal), * Belzona® 5811 (Immersion Grade),

Problem

Efficiency losses and pump breakdown due to severe erosion-corrosion of the single vertical axial flow pump (7090 m³/h). Prior to the Belzona solution the client had to replace or repair the pump components annually. As a significant local electricity supplier, downtime of this critical equipment caused major problems.









Photograph Descriptions

- * Original system after 1 year in service,
- * The finished Belzona application,
- * Cavitation damage in the swept area,
- * Ready to go back into service after touch up ,

Application Situation

Sea water cooling system pump for a 60 MW turbine.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflets CEP-5, CEP-3 and CEP-4.

Belzona Facts

The original bell lining was failing on an annual basis, leading to pitting corrosion and regular replacement. The Belzona repair vastly

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com



improved reliability and performance. The pump casing, liner and diffuser were also repaired and coated, internally and externally. Yearly touch up is required of the sacrificial coating in the swept area due to cavitation damage. original Belzona protected bellmouth still in service after nine years.

ISO 14001:2015 EMS 695213

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO 9000 Registered Quality Management System.

www.belzona.com

