

BELZONA REPAIRS LEAKING FLANGE CONNECTION ON TRANSFORMER

ID: 1484

Industry: Power
Application: VPF-Valves, Pipes and Fittings
Substrate: Steel
Products: * Belzona® 1161 (Super UW metal) ,

Customer Location: Electricity Distribution Company, UK
Application Date: 2006

Problem

Oil leaking from flanged pipe connections



Photograph Descriptions

- * Oil leaking from flange ,
- * Belzona® 1161 being applied ,
- * Inspection of Belzona® 1161 application ,

Application Situation

Oil filled Transformer

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11a.

Belzona Facts

Repairs were carried out in-situ without the need to take the transformer off-line. Belzona® 1161 was applied without having to drain the transformer oil. Repair was total success.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve