

BELZONA REPAIRS TRANSFORMER FLANGE OIL LEAK

ID: 1491

Industry: Buildings & Structures

Customer Location: Arizona, USA

Application: GSS-Gaskets, Seals and Shims


Application Date: July 1992

Substrate: Steel

Products: * Belzona 2221 (MP Fluid Elastomer) ,
* Belzona 1221 (Super E-Metal) ,

Problem

Oil leaks raised maintenance, EPA and safety concerns. Replacement of gaskets would require shut-down and dismantling of equipment.



Photograph Descriptions

- * 1. Oil leak area of transformer ,
- * 2. Seal with Belzona 1221, then pour Belzona 2221 encapsulated the flange ,
- * 3. Application completed ,

* ,

Application Situation

Flanged pipe connections on transformer flange at the major power company.

Application Method

The application was carried out in accordance with a modified of Belzona Know-How System Leaflet VPF-11 and GSS-4. Leaks were firstly stopped by using Belzona 1221. Mould was constructed and a fluid grade of Belzona 2221 was poured in to encapsulate the flange.

Belzona Facts

Repairs were carried out in-situ without the need to take the transformer off-line. Savings were estimated at \$150,000. The repaired

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com



flange was in continuous operation for over 4 years.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

