

REPARACION DE BLOCK DE MOTOR

ID: 1624

Industria: Energía

Solicitud: Motores y Carcasas

Sustrato: Acero

Productos: * Belzona® 1111 (Super Metal),
* Belzona® 9341(Rinforcement Tape),

Ubicación del cliente: Esen Generadores - Mar del Plata,
Argentina

Fecha de aplicación: Septiembre 2008

Problem

La rotura de una de las bielas del motor produjo la perforación del block del motor debido al fuerte impacto



Descripciones de fotografías

* ,

- * Vista del daño ,
- * Refuerzo metálico aplicados ,
- * Vista externa de la reparación ,
- * Vista del interior del block reparado ,

* ,

Situación de la aplicación

Perforación de block de motor

Método de aplicación

La reparación fue realizada de acuerdo a lo establecido en las técnicas ENC-1 y ENC-11. Se utilizó refuerzo metálico y sucesivas capas de Belzona® 1111 y Belzona® 9341

Datos de Belzona

El motor pertenece a un generador de energía el cual debía ser puesto en servicio de manera urgente. El cliente no contaba con otra alternativa que no sea el reemplazo del block, lo cual tendría una demora importante por falta de stock

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com



For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are

manufactured under an ISO

9000 Registered Quality

Management System.

www.belzona.com

