

BELZONA REPAIR ON 10,000 HP SULZER MARINE DIESEL ENGINE


ID: 249

Industry: *Marine*
Application: *ENC-Engines and Casings*
Substrate: *Cast Iron*
Products: ** Belzona® 1111 (Super Metal) ,*

Customer Location: *Shipping company in Ontario, Canada*
Application Date: *February 2001*

Problem

Pitting corrosion on engine block caused o-ring seals to leak.



Photograph Descriptions

- * View of Sulzer Engine ,
- * Close-up of pitted, corroded area on engine block ,
- * Prepared area after machining, before Belzona ,
- * View of machined Belzona ,

Application Situation

Six cylinder Sulzer Diesel Engine built in 1969.

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet ENC-5.

Belzona Facts

Each cylinder is 36" in diameter, each had three corroded lands about 4" wide. Customer felt conventional weld repairs would have been too risky, and that Belzona was the only viable alternative.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve