BELZONA REPAIRS AND PROTECTS ENGINE BLOCK AND CYLINDER LINERS

ID: 3641

Industry: General Industry Customer Location: German diesel engine refurbishment

company

Application: ENC-Engines and Casings Application Date: August 2005

Substrate: Cast Iron

Products: * Belzona® 1111 (Super Metal),

* Belzona® 1391 (Ceramic HT),

Problem

Corrosion and cavitation damage in cooling water area as well as leaking O-ring sealing surfaces.









Photograph Descriptions

- * Diesel engine block prior to repair,
- * Close-up of application area,
- * Close-up of application area,
- * Completed engine block application,

Application Situation

Ship diesel engine block

Application Method

The repair to the sealing faces was carried out in accordance with Belzona Know-How System Leaflet ENC-5, using machining methods. Areas damaged by corrosion and cavitation were rebuilt with Belzona® 1111, and cooling water areas were fully coated with Belzona® 1391 in accordance with Belzona Know-How System Leaflet ENC-6.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com

BELZONA®

Belzona Facts The client buys discarded engines which they recondition. As a result of rebuilding the engine block with Belzona it is classed as new and not as repaired thus offering better resale value as well as improved longevity through the use of non-corroding technology.