

# BELZONA REPAIRS NEW FLOATING HOSE SECTION DAMAGED IN TRANSIT

ID: 4818

Industry: Oil & Gas  
Application: SOS-Ships and Offshore Structures

Customer Location: Oil company, North Sea, UK  
Application Date: November 2011

Substrate: Rubber  
Products: \* Belzona 2211 (MP Hi-Build Elastomer) ,

## Problem

*Hose had been damaged in transit as a result of its fastenings coming loose. The hose had rubbed against its container frame.*



## Photograph Descriptions

\* 1. 15mm deep cuts in the floating hose cover 2. Application of reinforced system of Belzona 2211 3. Completed Belzona repair 4. Inspection of the hose 2 years later showing the Belzona application still in service ,

## Application Situation

Damaged floating hose section

## Application Method

Application was carried out in accordance with Belzona System Leaflet SOS-12. The surface of the hose was roughened prior to application of Belzona 2911 (QD Conditioner) followed by a reinforced system of Belzona 2211 to the damaged areas.

## Belzona Facts

The application was completed at a fraction of the cost of a replacement hose and has proved to be successful for 2 years.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve