

BELZONA REPAIRS CRACK ON ENGINE BLOCK

ID: 5270

Industry: *Pulp & Paper*
Application: *ENC-Engines and Casings*
Substrate: *Cast Iron*
Products: ** Belzona 1111 (Super Metal) ,*
** Belzona 9341 (Reinforcing Sheet) ,*

Customer Location: *Idaho, USA*
Application Date: *1992*

Problem

An early freeze allowed ice to crack the engine casing.



Photograph Descriptions

- * JD 444 Loader with cracked engine block ,
- * Engine showing long crack in water jacket ,
- * Area prepared with studs in place ,
- * Completed application ,

Application Situation

Cracked engine casing leaks antifreeze.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet ENC-1. The area was ground, studs placed every 2 inches then covered with Belzona 1111, incorporating Belzona 9341.

Belzona Facts

The engine ran strong. The leaking antifreeze was the only thing stopping them from using the loader. Replacing the engine was the only alternative for the sawmill.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve