BELZONA SEALED THE LOCK

ID: 5758

Industry: Power Customer Location: Dam, Oklahoma, USA

Application: FPA-Floor Problem Areas Application Date: 2004

Substrate: Concrete

Products: * Belzona 4111 (Magma-Quartz),

Problem

Damaged concrete below the seal plate let water leak into the lock.









Photograph Descriptions

- * Lumber placed in the lock,
- * Belzona 4111 built up damaged area,
- * Completed repair top view,
- * Completed repair side view,

Application Situation

Lock and Dam on the Arkansas River

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. 16 foot 2x4's were drilled and put into place on the dam. Plastic was used as a release agent and the void was filled with Belzona 4111.

Belzona Facts

Concrete was used once before and failed due to the lack of adhesion. A grout repair would take two weeks to cure. This repair allowed the lock to be back in service in one day.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve