BELZONA KEEPS THE LIGHT RAIL ON TRACK

ID: 5930

Industry: Transport

Application:

Substrate: Steel

Products: * Belzona 1221 (Super E-Metal),

Problem

The fiberglass joint spacer was breaking down and the top of the track was weakening and getting pushed into the void.







Customer Location: Seattle, WA, USA

Application Date: September 2015



Photograph Descriptions

- * Light Rail Joint; note the stress crack on the bottom-center of the joint,
- * Grinding to remove the fiberglass and prepare the surface,
- * Application of Belzona 1221,
- * Completed application ,

Application Situation

Steel train track for the city light rail transportation system.

Application Method

A cutting wheel was used to remove the damaged fiberglass piece and then a grinding wheel was used to roughen and prepare the two surfaces. Duct tape was applied on either side of the repair for fast and easy clean up. An appropriate amount of Belzona 1221 was mixed and first worked into the two faces of the track. Then, the material was pushed in from the top until excess squeezed out on both sides. The excess material was scraped off, leaving it a little proud. A grinder was then used to machine it down to the proper profile.

Belzona Facts

This repair took a couple hours to complete and the fast cure time allowed for the train to stay on schedule for its first morning run. The alternative process was either attempt to replace the fiberglass spacer or cut, remove and replace the section which would have cost considerable time and money.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.



www.belzona.com