# BELZONA PRESERVES 60-YEAR-OLD WATER PUMP FOR IRRIGATION DISTRICT

ID: 6037

Industry: Customer Location: *Arkansas, USA*Application: *CEP-Centrifugal Pumps*Application Date: *May 2015* 

Substrate: Cast Iron

Products: \* Belzona 1111 (Super Metal),

\* Belzona 1121 (Super XL-Metal),

\* Belzona 1341 (Supermetalglide),

#### Deizona 10 11 (dapermetaignae)

#### **Problem**

Flanges on the split line, wear ring fits, and packing areas were severely corroded, preventing the pump from sealing and made it very inefficient.









## **Photograph Descriptions**

- $^{st}$  Severe corrosion in body of the pump ,
- \* Close up of screws installed,
- \* Screws installed in split line and wear rings,
- \* Completed application to pump case,

# **Application Situation**

The case and fits of a 60-year-old pump.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve

## **Application Method**

The application was carried out in accordance with modified versions of Belzona Know-How System Leaflets CEP-3 and CEP-5. Because of the severe erosion/corrosion damage of the wear ring fits and split line, 2"+ thickness of Belzona 1111 was needed. Because of this, self tapping screws/bolts were installed to provide stability to Belzona 1111. After 1111 was installed, all fits were machined. Belzona 1341 was coated on all wetted surfaces.

### **Belzona Facts**

The pump was approximately 60 years old. Lead time for replacement was 14 months. Welding was not an option because the substrate was cast iron. Pump needed to be back in service in a very short amount of time. No alternatives were available on such a short notice.

www.belzona.com