

# Lorry Engine Repaired with Belzona


ID: 7576

Industry: *Transport*  
Application: *ENC-Engines and Casings*  
Substrate: *Cast iron*  
Products: *\* Belzona 1111 (Super Metal) ,*

Customer Location: *Transport company, Slovakia*  
Application Date: *2014*

## Problem

*Cracked block due to freezing over winter months.*



## Photograph Descriptions

- \* 1. Cracked engine ,
- \* 2. Crack detection to identify all cracks ,
- \* 3. Surface preparation ,
- \* 4. Belzona 1111 repair incorporating Belzona 9341 Reinforcement Tape. ,

## Application Situation

Lorry engine.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet ENC- 1

## Belzona Facts

Welding of this damage would take a long time and potentially cause more damage so repairing with Belzona 1111 was much better for customer.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve