

Belzona SuperWrap Allows Drilling to Continue

ID: 7630




Industry: Oil & Gas
Application: SOS-Ships and Offshore Structures

Customer Location: Azerbaijan
Application Date: November 2017

Substrate: ASTM A 519 Gr 4130
Products: * Belzona SuperWrap II ,

Problem

Due to long lead time fabricating new sections of pipe, Belzona SuperWrap was used to reinstate the required strength to keep the high pressure lines in operation for at least 1 year.



Photograph Descriptions

- * 1. View of Pipe before 21 wraps ,
- * 2. View of Pipe before 12 wraps ,
- * 3. View of SuperWrap repair: 21 wraps ,
- * 4. View of SuperWrap repair: 12 wraps ,

Application Situation

A platform off the coast of Baku had to stop drilling due to wall loss on the HP mud lines. The problem areas were on 3 bend sections.

Application Method

As per Belzona SuperWrap training

Belzona Facts

Drilling needed to commence immediately and due to long lead time to replace the pipe sections, Belzona SuperWrap was able to give the required up time.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve