

# **Belzona Repairs Diesel Engine**

ID: 8034

Oil & Gas	
n: ENC-Engines d	and Casings
Cast iron	
* Belzona 111	1 (Super Metal) ,
Cast iron	5

Customer Location: Croatia Application Date: July 2002

#### Problem

Pitting corrosion on engine block o-ring seats had caused failure.



### **Photograph Descriptions**

- \* Damaged area,
- \* Surface preparation,
- \* Belzona 1111 rebuild ,
- \* Belzona 1111 machined,

### **Application Situation**

100 cylinders required repairing or would be replaced.

### **Application Method**

The aplication was carried out in acordance with a modified version of Belzona Know-How System Leaflet ENC-5.

## **Belzona Facts**

Customer is the biggest oil company in Croatia and this is an ongoing job since 2002 untill today. No replacement was needed in all these years.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 FS 695214 ISO 14001:2015 EMS 695213 Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

www.belzona.com

