

# Belzona Chocking Repair on Gear Mounting

ID: 8061

Industry: General Industry

Customer Location: Szarbków, Poland

Application: GSS-Gaskets, Seals and Shims

Application Date: 2019

Substrate: Concrete

Products: \* Belzona 4111 (**Magma Quartz**),

\* Belzona 7111,

## Problem

Gear mounting not working at full efficiency due to misalignment. Repair work need to concrete area prior to chocking.



## Photograph Descriptions

- \* 1. Gear Equipment Picture ,
- \* 2. Application of Belzona 4111 ,
- \* 3. Application of Belzona 7111 ,
- \* 4. Chocking application complete. ,

## Application Situation

Re-levelling a steel foundation slab of a mill gear and the foundation of the mill on the plate.

## Application Method

The application was carried out in accordance with Belzona System Leaflet GSS-2. Placing of the steel foundation slab using the Belzona 4111. Chocking the foundation of the mill plate using Belzona 7111.

## Belzona Facts

Belzona won the chocking project over a competitor due to the competence and back up support of the local distributor.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve