

Pump case erosion damage repair in gravel mine

ID: 8589

Industry: Mining & Quarrying
Application: CEP-Centrifugal Pumps
Substrate: Cast iron (wear resistant)
Products: * Belzona 1812 was used to build up the whole material loss and subsequently a coat of Belzona 1321 was applied to smooth out the surface, this combination is the best possible solution to prevent or to slow down this erosion mechanism. ,

Customer Location: Hungary, Gravel mine
Application Date: 2021.02.20

Problem

The customers Warman WGR200 suffered from erosion because of the failure of the rubber lining the entrapped solid in the flow found route to the casing surface. The casing material wore until leakage.



Photograph Descriptions

- * 1-Deffective casing ,
- * 2-Deffective area ,
- * 3-Deffective area after sand blasting ,
- * 4-Finished application with 1321 top-coat ,

Application Situation

The customer, a gravel mine site operation leader, approached us to find a cost effective repair solution alternative to the case replacement. The answer was a simple yes and the quotation was sent.

Application Method

Hand application according to the CEP-06: For repair of holed/cracked casings

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

- Huge savings against the case replacement - Quick technical and financially favourable offer - Quick turnaround of the application

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com



Copyright © Belzona International Limited 2024