


Automotive Engine Block Repair

ID: 9538

Industry:	Transport	Customer Location:	Greece
Application:	ENC-Engines and Casings	Application Date:	September 2024
Substrate:	Aluminum		
Products:	Belzona 1212		

Problem
Cooling liquid leakage from engine block, on an Opel Astra J model, A14XER engine type.



Initial condition with prepared surface Start of application Super Metal Application Repair completed

Application Situation

The customer reported losing engine coolant liquid. The engine block leak's primary cause was identified by the workshop.

Application Method

Workshop cleaned and abraded the surface.

Belzona Facts

Belzona offered the local workshop a feasible solution for their client. The traditional repair method would be the engine replacement with a cost of about 3000 euros.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

