# **Cooling Tower Pipe Leak Repair**

ID: 9721

Industry:Oil & GasCustomer Location:Southwestern OntarioApplication:VPF-Valves, Pipes and FittingsApplication Date:November 2024


Substrate: Carbon steel

Products: Belzona 1212, Belzona 1982 (SuperWrap II), Belzona SuperWrap, Accessories, Belzona 9111 (Cleaner

Degreaser), Belzona 9611 (ES-Metal)

#### **Problem**

1 inch steel pipe had corrosion and was leaking at the pipe seam and socket weld joint









X-Ray showing the socket joints Picture showing pipe leaking. and pipes

Picture show's water leak has been stopped and application completed.

Picture show's water leak has been stopped and application completed.

#### **Application Situation**

The plant was not able to shut down the system so a solution for a live leak was requested and the end user and contractor knew Belzona would have a solution and the products for the application.

The cost was under \$3,000.00 for the repair that saved the plant from shutting down the system that would have cost hundreds of thousands of dollars 2/3 weeks of down time.

## **Application Method**

Heavy rust was removed by a tapping the pipe with a hammer and than the preparation was completed using pneumatic air hand tooling, needle gun and grinder.

### **Belzona Facts**

Belzona was chosen for the both the end user and contractor have used many Belzona products over the years and have great success and long term results.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

