

BELZONA PUMP REPAIR PROVIDES OVER TEN YEARS OF UNINTERRUPTED SERVICE

ID: 26

Industry: *Pulp & Paper*

Application: *CEP-Centrifugal Pumps*

Substrate: *Cast iron*

Products: ** Belzona® 1311 (Ceramic R Metal) ,
* Belzona® 1321 (Ceramic S Metal) ,*

Customer Location: *Paper Company in Georgia*

Application Date: *November 1986*

Problem

Pump suffered from erosion/corrosion and was completely destroyed after four years of operation



Photograph Descriptions

- * Severe damage ,
- * The wear ring seats rebuilt, clamps help ensure proper alignment ,
- * Belzona® 1321 (Ceramic S Metal) coating ,

Application Situation

Primary fan pump

Application Method

The application was carried out in accordance with Belzona Know-How Leaflets CEP-1, CEP-2 and CEP-3.

Belzona Facts

Pump replacement cost is \$60,000.00. Cost of Belzona repair: \$9,300.00. After more than ten years of uninterrupted service, the pump is still in use and twice required only minor touch-ups. An impressive savings of three pump replacements.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are

manufactured under an ISO

9000 Registered Quality

Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve