

BELZONA IDEAL SOLUTION FOR DAMAGED CONVEYOR BELT

ID: 3125

Industry: *Pulp & Paper*

Application: *SHM-Solids Handling Machinery*

Customer Location: *Paper Mill, São Paulo, Brazil*

Application Date: *September 2011*

Substrate: *Rubber*

Products: ** Belzona® 2311 (SR Elastomer),*

Problem

The fork lift driver caught the conveyor belt while he was loading the paper, stopping the process and tearing the belt.



Photograph Descriptions

- * Conveyor belt damage ,
- * Preparation and conditioning with Belzona® 2911 ,
- * Belzona® 2311 being applied and incorporating Belzona® 9341 (Reinforcement Tape) ,
- * Job done ,

Application Situation

Conveyor belt is used to process recycled paper. A fork lift is used to load paper onto the belt.

Application Method

The application was carried out in accordance with Belzona Know-How system Leaflet SHM-1. Top cover was cut back before repairing with Belzona® 2311 incorporating Belzona® 9341 (Reinforcement Tape).

Belzona Facts

The application was done in 2 hours and the equipment was back in service with minimal delay. To replace or repair the belt conventionally would have involved an emergency call out from specialist contractor who would have had to travel from another city. Costs and time delay were unacceptable.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve