

BELZONA DIESEL ENGINE BLOCK RESTORED

ID: 32

Industry: *Marine*
Application: *ENC-Engines and Casings*
Substrate: *Cast steel*
Products: ** Belzona® 1111 (Super Metal) ,*

Customer Location: *Ship Repair Company in Florida*
Application Date: *August 1995*

Problem

Connecting rod went through the side of the casing, severely damaging the engine block



Photograph Descriptions

* Damaged engine block In the engine room, work in progress The finished repair ,

Application Situation

Hitachi diesel engine of a ship

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet ENC-1.

Belzona Facts

Replacement cost of the engine block is greater than \$50,000. The total cost of the repair including labor and materials was \$5,180. The vessel's owner saved over \$45,000.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve