

# BELZONA REPAIRS BROKEN HYDRO ELECTRIC TURBINE RUNNER

ID: 4674

Industry: Power Customer Location: Hydro Electric Plant, USA

Application: CEP-Centrifugal Pumps Application Date: May, 2007

Substrate: Cast steel

Products: \* Belzona® 1311 (Ceramic R-Metal) Belzona® 1321 (Ceramic S-Metal) Belzona® 1341 (Supermetalglide) ,

#### Problem

Loss of balance and horsepower.









## **Photograph Descriptions**

\* Broken runner blade Expanded metal tack welded Blades rebuilt with Belzona® 1311 Completed application after coating runner,

## **Application Situation**

Wicket gate came loose and fell into turbine breaking three blades on runner.

## **Application Method**

Application was carried out in accordance with the Belzona Know-How System Leaflets CEP-1 & CEP-3. Expanded metal was tack welded in place before rebuilding with Belzona® 1311. Complete runner was coated with Belzona® 1311 and Belzona® 1341 was applied on top to improve fluid flow efficiency.

### **Belzona Facts**

The efficiency gain was so profound, that the customer was able to reduce the water setting from 70% to 62% without changing the power output from the runner, maintaining the 500 kW output. Using less water, the water behind the dam lasts longer, keeps the turbine running longer, resulting in increased revenue across a year. Belzona solution cost 9.2% of the conventional replacement by repairing the turbine instead of tearing it down and sending it out to be repaired. While the conventional repair would take 10 weeks of downtime, Belzona refurbishment took 2 weeks. The customer's payback period on this repair was 3 months. Three years later and the turbines still have good horsepower with the runner blades still intact.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve