NON-COMPLIANT WRAP KEEPS 30" LINE IN SERVICE

ID: 4812

Industry: Oil & Gas Customer Location: New Jersey, USA

Application: VPF-Valves, Pipes and Fittings Application Date: December 2012

Substrate: Carbon Steel

Products: * Belzona 1111 (Super Metal),

* Belzona 9341 (Reinforcement Tape) ,

* Belzona 1971 (Superwrap Conditioner),

* Belzona 9371 (Superwrap Reinforcement Sheet),

* Belzona 5811 (Immersion Grade),

Problem

Holes and thin wall.









Photograph Descriptions

- * 30" diameter effluent line at a petroleum terminal in NJ.,
- * Holes and thin wall revealed.,
- * Applying a second layer of Belzona 1111 over the first wrap. ,
- * Two coats of Belzona 5811 was applied over the finished wrap repair.,

Application Situation

The 30" diameter effluent line had three separate areas where corrosion and thin wall pipe allowed a large amount of water to pond near an access walk and traffic area. With winter coming, the plant wanted to fix the leaking piping and eliminate the potential safety issues of icy conditions on the access walk and traffic area. Operating pressure is <5 psi. Water would have to be

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com



diverted from the piping for repairing three (3) separate areas.

Application Method

Surface was prepared by abrasive blasting to SSPC-SP10 near white. Patches were made to holed areas using Belzona 1111/Belzona 9341 in accordance to a modified version of VPF-11a, Low Pressure. Then Belzona 1111 was applied to the entire outer surface and wrap of Belzona 1971 wetted out Belzona 9371 was applied with a 50% overlap. A second layer of Belzona 1111 was applied along with a second wrap of Belzona 1971/Belzona 9371. It was completed by adding a Belzona 5811 coating.

Belzona Facts

The only other option that was being considered was replacing the piping at a cost that was 3 to 4 times the price of the Belzona repair. Other Belzona repair systems that had been done at the plant gave them confidence that the wrap repair would last.