

BELZONA REPAIRS NEW FLOATING HOSE SECTION DAMAGED IN TRANSIT

ID: 4818

Industry: Oil & Gas
Application: SOS-Ships and Offshore Structures

Customer Location: Oil company, North Sea, UK
Application Date: November 2011

Substrate: Rubber
Products: * Belzona 2211 (MP Hi-Build Elastomer) ,

Problem

Hose had been damaged in transit as a result of its fastenings coming loose. The hose had rubbed against its container frame.



Photograph Descriptions

* 1. 15mm deep cuts in the floating hose cover 2. Application of reinforced system of Belzona 2211 3. Completed Belzona repair 4. Inspection of the hose 2 years later showing the Belzona application still in service ,

Application Situation

Damaged floating hose section

Application Method

Application was carried out in accordance with Belzona System Leaflet SOS-12. The surface of the hose was roughened prior to application of Belzona 2911 (QD Conditioner) followed by a reinforced system of Belzona 2211 to the damaged areas.

Belzona Facts

The application was completed at a fraction of the cost of a replacement hose and has proved to be successful for 2 years.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve