## BELZONA SETS ANCHOR AT THE GEARBOX BASE OF ROD MILL

ID: 4893

Industry: Mining & Quarrying Customer Location: Mine, AM, Brazil
Application: FPA-Floor Problem Areas Application Date: December 2011
Substrate: Reinforced Concrete

Products: \* Belzona 4111 (Magma-Quartz),

\* Belzona 4151 (Magma-Quartz Resin),

#### **Problem**

There was a need to install reinforcement at the anchoring of the concrete with base plate of the gearbox, with the addition of four extra intermediate anchors that could be set efficiently. Return to service needed to be as quick as possible as the damaged base was causing the equipment to break.







# **Photograph Descriptions**

- \* Damaged gearbox base causing excessive vibration,
- \* Base holes to anchor's housing,
- \* Anchors set according to template,

## **Application Situation**

There was a need to set intermediate anchors with a fast curing material with efficient anchorage on concrete base.

## **Application Method**

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-10.

#### **Belzona Facts**

Belzona solution offered fast and efficient repair. Cure time was minimum, meeting client's expectations.

