RUBBER LINER IN SLURRY PUMP REPAIRED WITH BELZONA

ID: 4935

Industry: Mining & Quarrying Customer Location: Quarry, Israel
Application: SHM-Solids Handling Machinery Application Date: February 2014

Substrate: Rubber

Products: * Belzona 2311 (SR Elastomer),

Problem

The rubber liner had suffered local damage resulting in an operational shutdown.









Photograph Descriptions

- * Damaged rubber liner,
- * The Warman 10/8M pump,
- * Damaged area Conditioned with Belzona 2911 (Elastomer QD Conditioner),
- * Rubber liner after application of Belzona 2311,

Application Situation

Rubber lined Warman 10/8M slurry pump.

Application Method

Application was carried out in accordance with Belzona Know How System Leaflet SHM-9.

Belzona Facts

The costumer was able to run the pump the same day saving shutdown costs of 7 days whilst waiting for new replacement liner.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve