

BELZONA REPAIRS A CRACKED ENGINE BLOCK


ID: 5366

Industry: *General Industry*
Application: *ENC-Engines and Casings*
Substrate: *Cast Iron*
Products: ** Belzona 1111 (Super Metal) ,*

Customer Location: *WA, USA*
Application Date: *1992*

Problem

Engine block cracked by freezing water.



Photograph Descriptions

- * Drilling holes along crack ,
- * Threading holes ,
- * Studs installed, grinding surface ,
- * Reinforced Belzona 1111 applied to seal the crack ,

Application Situation

John Deer engine block.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet ENC-1.

Belzona Facts

The only alternative was to replace the block. Instead, \$50.00 of Belzona 1111 was used to solve the problem.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve