

Ремонт двигателя РЕНО 5000

ID: 5968

Промышленн *General Industry*

ость:

Заявление: *ENC-Engines and Casings*

Субстрат: *Чугун*

Продукты: ** Belzona 1111 ,*

Местоположение *Россия, Татарстан*


клиента:

Дата подачи *Май 2011 г.*

документов:

Problem

Эксплуатация двигателя с отверстием в блоке цилиндров невозможна. Требуется покупка нового блока.



Описание фотографий

* 1. Общий вид повреждения 2. Повреждение крупным планом 3. Заделанное отверстие вид изнутри 4. Заделанное отверстие вид снаружи ,

Ситуация с приложением

При эксплуатации двигателя большегрузного автомобиля произошел срыв шатуна рабочего цилиндра. При этом возникло сквозное отверстие в блоке цилиндров.

Способ применения

ENC-1

Белзона Факты

Для возврата в строй двигателя было необходимо купить новый блок цилиндров. Применение материалов и технологии Belzona позволило уменьшить расходы на восстановление двигателя в несколько раз. На сегодняшний день замечаний нет.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products
are manufactured
under an ISO 9000
Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Ремонт • Защита • Улучшение

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015 Belzona products
FS 695214 are manufactured
ISO 14001:2015 under an ISO 9000
EMS 695213 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2024

