BELZONA FILLS THE GAP BETWEEN SKID AND DECK

ID: 6042

Industry: Oil & Gas Customer Location: Gulf of Mexico, USA

Application: SOS-Ships and Offshore Structures Application Date: February 2016

Substrate: Carbon Steel

Products: * Belzona 1121 (Super XL-Metal),

* Belzona 2211 (MP Hi-Build Elastomer), * Belzona 3111 (Flexible Membrane), * Belzona 3921 (GSC Surface Conditioner), * Belzona 9111 (Cleaner Degreaser),

* Belzona 9331 (MR7 Reinforcement Sheet),

Problem

To avoid water and debris from getting between the skid and deck, the gap between the two had to be sealed. Hot work would take weeks to weld the entire perimeter as the gap was 1.5" in some places. The seal also needed to be flexible to absorb any possible vibration.









Photograph Descriptions

- * Gap between skid and deck.,
- * Holes in deck repaired with Belzona 1121.,
- * Surfaces primed with Belzona 3921 and gap filled with Belzona 2211. Belzona 9331 is test fitted to bridge interface.,
- * Completed application with Belzona 3111.,

Application Situation

A new skid package was welded to the deck but did not sit flush, due to uneven surfaces. The deck was losing metal from corrosion and had sevral holes in it.

Application Method

The areas of the deck suffering from metal loss were repaired with Belzona 1121. Then, all surfaces were primed with Belzona 3921 prior to using Belzona 3111 as a flexible sealant. The gap between the deck and skid was filled with Belzona 2211. Belzona 9331 was

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve

saturated with Belzona 3111 to bridge over interface.

Belzona Facts

Welding this gap would have caused a shut-in with loss of production. To repair the gap between the skid and deck with hot work would require weeks to complete the repair. The Belzona solution saved the customer time and provided a repair that was also flexible to absord possible vibrations.