# PRESS ROLL CRACK REPAIR WITH BELZONA

ID: 616

Industry: Pulp & Paper Customer Location: Pulp and paper mill, Egypt

Application: SHM-Solids Handling Machinery Application Date: December 2004

Substrate: Hard rubber

Products: \* Belzona® 1111 (Super Metal),

Problem

Crack in the hard rubber cover of the press roll. The crack was increasing over time.









## **Photograph Descriptions**

- \* The crack in the rubber cover,
- \* Removing the cracked layer,
- \* Belzona $^{\rm @}$  1111 applied to the roll ,
- \* Completed repair,

### **Application Situation**

Press roll

#### **Application Method**

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-9. The cracked layer was removed then Belzona® 1111 applied and finally machined back to size.

#### **Belzona Facts**

Belzona® 1111 had similar hardness to the original hard rubber, was easy to machine and has good compressive strength to cope with the operating conditions.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve