PRESS ROLL CRACK REPAIR WITH BELZONA

Industry:Pulp & PaperApplication:SHM-Solids Handling Machinery

Customer Location: *Pulp and paper mill, Egypt* Application Date: *December 2004*

Substrate:Hard rubberProducts:* Belzona® 1111 (Super Metal) ,

Problem

Crack in the hard rubber cover of the press roll. The crack was increasing over time.



Photograph Descriptions

- * The crack in the rubber cover ,
- * Removing the cracked layer,
- * Belzona® 1111 applied to the roll ,
- * Completed repair,

Application Situation

Press roll

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-9. The cracked layer was removed then Belzona[®] 1111 applied and finally machined back to size.

Belzona Facts

Belzona[®] 1111 had similar hardness to the original hard rubber, was easy to machine and has good compressive strength to cope with the operating conditions.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 FS 695214 ISO 14001:2015 EMS 695213

Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

www.belzona.com



ID: 616