

Belzona repairs damaged turbine flange face

ID: 7570

Industry: *General Industry*

Customer Location: *Chemical plant, Slovakia*

Application: *ENC-Engines and Casings*

Application Date: *2010*

Substrate: *Cast iron.*

Products: ** Belzona 1591 - Belzona 1593 would now be recommended. ,*

Problem

Wet steam caused erosion corrosion damage to flange face of turbine casing. This damage meant steam leakage from the turbine.



Photograph Descriptions

- * 1. Damaged turbine split casing ,
- * 2. Glass panel (coated with Belzona 9411 Release agent) used to form flat surface on Belzona ,
- * 3. Repaired area ,
- * 4. Turbine ready for mounting ,

Application Situation

Split casing of steam turbine.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet ENC-7.

Belzona Facts

Disconnecting, montage and transport would be very expensive for customer. Belzona repair is very quick and minimized outage of the turbine.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve