

Lorry Engine Repaired with Belzona

ID: 7576

Industry: *Transport*
Application: *ENC-Engines and Casings*
Substrate: *Cast iron*
Products: ** Belzona 1111 (Super Metal) ,*

Customer Location: *Transport company, Slovakia*
Application Date: *2014*

Problem

Cracked block due to freezing over winter months.



Photograph Descriptions

- * 1. Cracked engine ,
- * 2. Crack detection to identify all cracks ,
- * 3. Surface preparation ,
- * 4. Belzona 1111 repair incorporating Belzona 9341 Reinforcement Tape. ,

Application Situation

Lorry engine.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet ENC- 1

Belzona Facts

Welding of this damage would take a long time and potentially cause more damage so repairing with Belzona 1111 was much better for customer.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve