

# Belzona SuperWrap Allows Drilling to Continue

ID: 7630

Industry: Oil & Gas  
Application: SOS-Ships and Offshore Structures

Customer Location: Azerbaijan  
Application Date: November 2017

Substrate: ASTM A 519 Gr 4130  
Products: \* Belzona SuperWrap II ,

## Problem

Due to long lead time fabricating new sections of pipe, Belzona SuperWrap was used to reinstate the required strength to keep the high pressure lines in operation for at least 1 year.



## Photograph Descriptions

- \* 1. View of Pipe before 21 wraps ,
- \* 2. View of Pipe before 12 wraps ,
- \* 3. View of SuperWrap repair: 21 wraps ,
- \* 4. View of SuperWrap repair: 12 wraps ,

## Application Situation

A platform off the coast of Baku had to stop drilling due to wall loss on the HP mud lines. The problem areas were on 3 bend sections.

## Application Method

As per Belzona SuperWrap training

## Belzona Facts

Drilling needed to commence immediately and due to long lead time to replace the pipe sections, Belzona SuperWrap was able to give the required up time.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve