

Transformer Damaged by a Forklift Repaired with Belzona

ID: 7672

Industry: General Industry

Application:

Substrate: Steel


Products: * Belzona 1212 ,

Customer Location: Oregon, USA

Application Date: January 3, 2018

Problem

Forklift hit the cooling fins on an electrical transformer causing a serious oil leak.



Photograph Descriptions

- * 1. Note the oil dripping. ,
- * 2. Damage is severe, bending the cooling fin. ,
- * 3. & 4. Belzona 1212 applied, repair complete. ,

Application Situation

Electrical transformer cooling fin damaged by a forklift at a local recycling center.

Application Method

The trained Belzona contractor received a call about a leaking transformer. The caller was happy to hear that Belzona would be used for the repair as they had been a Belzona user for some time. The contractor tried doing a live leak repair but the oil was coming out too fast. Next he hooked up a vacuum pump to the transformer pulling about -5 pounds. This stopped the oil flow, Belzona 1212 was applied for a permanent repair.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

Belzona Facts

The only alternative would have been to drain the oil from the transformer and replace the cooling fin. Due to the age of the transformer a replacement was not likely.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

