

Belzona Chocking Repair on Gear Mounting

ID: 8061

Industry: General Industry

Customer Location: Szarbków, Poland

Application: GSS-Gaskets, Seals and Shims

Application Date: 2019

Substrate: Concrete

Products: * Belzona 4111 (Magma Quartz),

* Belzona 7111,

Problem

Gear mounting not working at full efficiency due to misalignment. Repair work need to concrete area prior to chocking.



Photograph Descriptions

- * 1. Gear Equipment Picture ,
- * 2. Application of Belzona 4111 ,
- * 3. Application of Belzona 7111 ,
- * 4. Chocking application complete. ,

Application Situation

Re-levelling a steel foundation slab of a mill gear and the foundation of the mill on the plate.

Application Method

The application was carried out in accordance with Belzona System Leaflet GSS-2. Placing of the steel foundation slab using the Belzona 4111. Chocking the foundation of the mill plate using Belzona 7111.

Belzona Facts

Belzona won the chocking project over a competitor due to the competence and back up support of the local distributor.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve