

MAINTENANCE OF BELZONA COATED SEPARATOR AFTER 9 YEARS IN SERVICE

ID: 835

Industry: Oil & Gas
 Application: TCC-Tanks and Chemical Containment Areas
 Substrate: Carbon Steel
 Products: * Belzona® 1111 (Super Metal) ,
 * Belzona® 1391 (Ceramic HT) ,

Customer Location: North Sea Platform, UK
 Application Date: Nov 1997

Problem

Previous glass flake system had failed and had suffered corrosion damage to the vessel wall. Belzona inspected after 9 years and only problems caused by local areas of mechanical damage.



Photograph Descriptions

- * Vessel being coated in 1997. ,
- * Vessel inspection in 2006. ,
- * Vessel Inspection 2006. ,
- * Localised Repair 2006. ,

Application Situation

In situ re-coat of the 1st stage separator in a time restricted shut down. Inspection in August 2006.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-3.

Belzona Facts

After 9 years in service, the vessel was returned to service with only the need for localized repairs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
 FS 695214
 ISO 14001:2015
 EMS 695213

Belzona products are
 manufactured under an ISO
 9000 Registered Quality
 Management System.

www.belzona.com


BELZONA
 Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

