

Восстановление посадочного места под подшипник на валу вентилятора

ID: 8401

Промышленность:

Местоположение Пивоваренный завод
клиента: г.Казань, Республика
Татарстан

Заявление:

Дата подачи документов: Октябрь 2020

Субстрат: Сталь

Продукты: * Belzona 1111 (Super Metal) ,

Problem

В процессе эксплуатации оборудования вышел из строя подшипник. Обойму подшипника провернуло, что привело к повреждению вала.



Описание фотографий

- * 1. Поврежденный вал ,
- * 2. Подготовка поверхности и нанесение материала Belzona 1111 ,
- * 3. Установка оправки ,
- * 4. Внешний вид восстановленного вала ,

Ситуация с приложением

Вал Высокопроизводительного Вентилятора Сушильного Аппарата Солодовни

Способ применения

Ремонт был проведен в соответствии с системными листовками Belzona MPT-2.

Белзона Факты

Из за простоя оборудования завод нёс многомиллионные убытки. Ремонт произведен в течении

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products
are manufactured
under an ISO 9000
Registered Quality
Management System.

www.belzona.com


BELZONA
Ремонт • Защита • Улучшение

двух дней с учетом изготовления оправки.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015 Belzona products
FS 695214 are manufactured
ISO 14001:2015 under an ISO 9000
EMS 695213 Registered Quality
Management System.

www.belzona.com

