

Belzona helps a manufacturer of aeroplane components

ID: 8542

Industry: Transport

Application: CEP-Centrifugal Pumps

Substrate: Cast iron

Products: * Belzona 1111 (Super-Metal) ,
* Belzona 2141 (ACR-Fluid Elastomer) ,

Customer Location: Tunisia

Application Date: June 2021

Problem

Severely damaged rubber linings. Presence of three cracks after surface preparation.



Photograph Descriptions

- * 1 : Damaged rubber linings ,
- * 2 : Cracks repair with Belzona 1111 (Super-Metal) and Belzona 9341 (Reinforcement Tape) ,
- * 3 : Application of first coat of Belzona 2141 (ACR-Fluid Elastomer) with the Reinforcement Tape Belzona 9341 ,
- * 4 : Completed application ,

Application Situation

During inspection, localised damage to the rubber linings caused by wear and abrasion was noted

Application Method

The application was carried out in accordance with Belzona System Leaflets TCC-1 and CEP-3 Cracks were repaired with Belzona 1111 and 9341, then two coats of Belzona 2141 with reinforcement tape belzona 9341 were applied to replace the damaged rubber linings.

Belzona Facts

The Belzona solution was applied in two days without the need to remove the equipment from site allowing a rapid return to

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Copyright © Belzona International Limited 2025

service.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

