# **Repair of Wind Turbine Bearing Sockets with Belzona**

ID: 8556

Industry:PowerCustomer Location: PolandApplication:MPT-Mechanical Power TransmissionApplication Date: August 2021

Substrate: Steel

Products: \* Belzona 1111 (SuperMetal),

**Problem** 

Knockout of bearing sockets - manifested by loud, irregular operation of wind turbine gears.







## **Photograph Descriptions**

- \* Image 1: Bearing Socket,
- \* Image 2: Bearing Socket in Situ with Belzona 1111 Applied,
- \* Image 3: Bearing sockets re-built with Belzona 1111,
- \* Image 4: bearing back in situ.,

## **Application Situation**

A wind turbine required a regeneration of wind turbine gear bearing sockets to be restored to it's original profile.

## **Application Method**

Applied in accordance with Belzona system leaflet MPT-7.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve

## **Belzona Facts**

Belzona 1111 can be applied in situ with a fast return to service. 100% solid material there is no shrinkage allowing a regeneration of the original bearing socket to it's previous profile, saving time and money due to a reduced downtime and no specialist equipment required.

www.belzona.com